EGS ISN
Clear and Synchronize

CG-DI

Remove EGS computer and connect OBD according to software wiring diagram

After the connection is correct, open the software and click on "EGS ISN"

BMW EGS ISN   Feature version:0001

VIN: WBA1A12070VV26419

SWFL_00000C55_077_133_096
SVK 12   [2016/12/08]
HWEL_0000022A_004_012_003
BTLD_00000C7C_012_068_001
SWFL_00000A81_000_077_000
SWFL_00000C55_077_133_096
SVK 13   [2018/04/29]
HWEL_0000022A_004_012_003
BTLD_00000C7C_012_068_001
SWFL_00000A81_000_077_000
SWFL_00000C55_077_133_096

OBD is connecting
OBD KWP-CAN 500kbps connection is successful

Number of programming files:

Wiring diagram

EGS status

Clear ISN

Reset Adapter

Automatically connect to view relevant information

BMW EGS ISN   Feature version:0001

VIN: WBA1A12070VV26419

SWFL_00000A81_000_077_000
SWFL_00000C55_077_133_096
SVK 12   [2016/12/08]
HWEL_0000022A_004_012_003
BTLD_00000C7C_012_068_001
SWFL_00000A81_000_077_000
SWFL_
SVK 13
HWEL_
BTLD_
SWFL_
SWFL_

OBD
OBD KWP CAN 500kbps connection is successful

Prompt

The EGS will be programmed. Please ensure that the car battery has enough power. Please keep the device cable connection during the programming process.

是(Y)   否(N)

Wiring diagram

EGS status

Clear ISN

Reset Adapter

Number of programming files:

Click the"Clear ISN", Maintain enough voltage

1. Confirm the VIN
2. Support modification

Programming module

BMW EGS ISN   Feature version:0001

VIN: WBA1A12070VV26419

SWFL_00000A81_000_077_000
SWFL_00000C55_077_133_096
SVK 12   [2016/12/08]
HWEL_0000022A_004_012_003
BTLD_00000C7C_012_068_001
SWFL_00000A81_000_077_0 0
SWFL_00000C55_077_133_0 6
SVK 13   [2018/04/29]
HWEL_0000022A_004_012_0 3
BTLD_00000C7C_012_068_0 1
SWFL_00000A81_000_077_0 0
SWFL_00000C55_077_133_0 6

Prompt

EGS ISN Cleared

确定

Flash is being erased
erase Flash success
The ECU is being programmed
ECU programming succeed
is verifying Flashs
verify that Flash is correct

100%

Number of programming files: 2/2

Wiring diagram

EGS status

Clear ISN

Reset Adapter

EGS ISN Cleared

After the successful completion, the connection will be terminated and the car will be automatically synchronized