

How to solve the central display unable light up after done Programming ?

First of all, we go BMW diagnosis to check the trouble code



Read the fault code, click to clear all vehicle faults



It is found that the transport mode is activated and needs to exit manually.



Click Cas4 Key Matching (OBD)



Software promote "Programming pre-processing"

Click "No"



Message Promote "Going to programming ECU, please ensure that battery power enough, and keep cable connected well with device"

Click "NO"



Click "Exit Transport Mode", DONE!

CAS4钥匙匹配 功能版本:0006

ECU信息: VIN: LBVCU1108DSG51909 Cas版本: CAS4PLUS 里程: 83776 钥匙频率: 315 底盘: F010

HWEL_0000007_006_000_005 HWAP_000002EA_255_255_255 BTLD_0000074B_007_001_001 SWFL_0000074F_007_012_000 SWFL_0000074D_007_012_000 SWFL_0000074E_007_012_000 SWFL_0000074C_007_012_000 CAFD_0000000F_005_025_058	钥匙号	钥匙ID	钥匙类型	状态
	1	60015A33	已使用	启用
	2	66FB5933	已使用	启用
	3	76B15634	已使用	启用
	4	265D2937	已使用	禁用
	5	FFFFFFFF	未使用	启用
	6	FFFFFFFF	未使用	启用
	7	FFFFFFFF	未使用	启用
	8	FFFFFFFF	未使用	启用
	9	FFFFFFFF	未使用	启用

OBD正在连接
OBD KWP-CAN 500kbps连接成功

CGDI TOOL
- WWW.CGDI.TC 查看帮助

生成经销商钥匙
恢复设码
删除钥匙
启用钥匙
禁用钥匙
里程重置
退出运输模式
修复ECU
更换CAS4

CAS4钥匙匹配 功能版本:0006

ECU信息: VIN: LBVCU1108DSG51909 Cas版本: CAS4PLUS 里程: 83776 钥匙频率: 315 底盘: F010

HWEL_0000007_006_000_005 HWAP_000002EA_255_255_255 BTLD_0000074B_007_001_001 SWFL_0000074F_007_012_000 SWFL_0000074D_007_012_000 SWFL_0000074E_007_012_000 SWFL_0000074C_007_012_000 CAFD_0000000F_005_025_058	钥匙号	钥匙ID	钥匙类型	状态
---	-----	------	------	----

OBD正在连接
OBD KWP-CAN 500kbps连接成功
正在退出运输模式
退出运输模式成功

CGDI TOOL
- WWW.CGDI.TC 查看帮助

生成经销商钥匙
恢复设码
删除钥匙
启用钥匙
禁用钥匙
里程重置
退出运输模式
修复ECU
更换CAS4